Intelligence System

WARNING: Do not remove until the end-user has read this notice.

Notice

- The Intelligence System **does not control the cold room's temperature.** It merely monitors it. However, it does control lighting.
- To obtain **programming instructions**, visit the Customer Zone page of Norbec's site at <u>www.norbec.com</u> or contact our Customer Service Department at (450) 449-1499 or, toll free, at (877) 667-2321.
- The Intelligence System temperature alarm includes an outlet (either NO or NC dry contact as selected) that can be easily connected to the buildings alarm system. This simple connection could help to avoid major losses in terms of food spoilage should a refrigeration system malfunction occur.
- It is recommended that each Intelligence Module outlet be fuse protected since a short circuit on either outlet could damage the control module and such damage is **not covered by the warranty**.

Troubleshooting

- If the display flashes while indicating 10 °C (50 °F), the cold room temperature has climbed above this value.
- If the display flashes while indicating -30 °C (-22 °F), the temperature sensor is incorrectly connected.
- If the temperature indicated by the display is higher than the cold room actual temperature, the hole where the sensor passes through the panel may be badly insulated. The sensor's reading may also be affected by the heating elements activated during the refrigeration system's defrost cycle.

Programming instructions on Norbec's site www.norbec.com